

Wheel Loader Bucket Interchangeability



NON-Interchangeability Reasons	
[1]	WA200-1 not interchangeable with WA200-5 due to differing pin up locations (boom pin hinge and bucket pin hinge have different widths in mounting position)
[2]	WA250-3 not interchangeable with WA250-5 due to different boom and bucket link pin sizes (also tilt stopper has different mounting position)
[3]	WA500-3 not interchangeable with WA500-6 due to differing pin up locations (boom pin hinge and bucket pin hinge have differing widths, also boom pin and bucket link pin mounting holes have different diameters)
[4]	WA600-3 not interchangeable with WA600-6 due to different pin up configurations (boom pin diameter is different, boom and bucket link hinges have different clearances and widths, etc.)
[5]	WA800-2 not interchangeable with WA800-3 due to different pin up configurations (boom pin and bucket link pin have different diameters, boom pin has different mounting position, boom pin and bucket link pins have different lock bolt hole locations)
[6]	WA470-8 not interchangeable with WA475-10 due to different link pin hinge width
[7]	Pin up dimensions are the same between WA900-3 and WA900-8. WA900-3 bucket may interfere on WA900-8 due to WA900-8 boom shape. WA900-8 bucket can be installed on WA900-3.

Revision Date: 11/26/2019