



**Make:** Komatsu  
**Model:** D39PX-23  
**Stock #:** U224523  
**Serial number:** 90832  
**Year:** 2015  
**Hours:** 3,670  
**Category:** Dozer  
**Location:** Lansing  
**Total price:** \$119,900.00  
**Pad width:** 28"  
**Transmission type:** Hystate  
**Bucket size:** 128"  
**Cab / ROPS:** Cab W/  
Heat&A/C  
**Classification:** AIS - C



# Machine Summary

YEAR	MAKE	MODEL	SERIAL NUMBER	STOCK NUMBER	PRICE
2015	Komatsu	D39PX-23	90832	U224523	\$119,900

## Certification C



- Extensive multi-point inspection performed by trained technicians
- Meets or exceeds wear criteria for certification class
- Planned Maintenance lube service completed
- Powertrain parts warranty included
- All machines work-ready

CERTIFICATION CLASS	A	B	C
Overall Certification			✓
Age / Hours	✓		
Appearance	✓		
Engine Powertrain	✓		
Hydraulics			✓
Chassis	✓		
Electrical	✓		
Ground Engaging	✓		
Warranty			✓

# Certification Guidelines - Dozer

CATEGORY	(A) <4,000 Hrs.	(B) <8,000 Hrs.	(C)
<b>RADIATOR</b>	No leaks, Dry, No damage	No leaks, Dry	No leaks
<b>ENGINE</b>	Starts and runs very well. No leaks. Minimal blowby. RPMs at spec	Starts and runs well. Minor leaks. Moderate blowby. RPMs at spec	Starts and runs. No major leaks Blowby not excessive.
<b>TRANSMISSION, FINAL DRIVES, AND STEERING</b>	No leaks Works properly in all speeds. Pressures good. Steers straight.	Minor leaks Works properly in all speeds. Pressures good. Steers straight.	No major leaks Drives and steers.
<b>UNDERCARRIAGE, OVERALL</b>	75%+ of Wear Life Remains	50% of Wear Life Remains	25% of Wear Life Remains
<b>BLADE FACE AND EDGE</b>	75%+ of Wear Life Remains	50% of Wear Life Remains	25% of Wear Life Remains
<b>BLADE PIN AND BUSHING</b>	75%+ of Wear Life Remains	50% of Wear Life Remains	25% of Wear Life Remains
<b>HYDRAULICS</b>	No leaks Pressures in spec	No external leaks Pressures in spec	No major leaks
<b>CYLINDERS</b>	No internal or external leaks	No external leaks	No major leaks
<b>ATTACHMENTS AND PINS</b>	75% + of Wear Life Remains	50% of Wear Life Remains	25% of Wear Life Remains
<b>DRAW BAR</b>	Required	Required	Not Required
<b>ROPS</b>	Required	Required	Required
<b>CAB, GLASS, SEAT, SEATBELT</b>	Good cond, clean, no tears in seat cushions, no cracked glass. Seat belt good.	Good condition, No tears in seat cushion, no cracked glass. Seat belt good.	Clean, No missing glass, Seat belt good.
<b>METAL</b>	No damage outside. All handles, guards, steps in place and all doors working	Minor damage. All handles, guards, steps in place and doors working	Damage allowed on non-critical panels. Doors working.
<b>ELECTRICAL</b>	All gauge/monitor panels work properly along with all enabled options. All Lights work properly Back up alarm works No Active fault codes	All gauge/monitor panels work properly along with all enabled options. Lights working properly Back up alarm works No critical active fault codes.	Critical gauges/monitor working. Work lights function Back up alarm works
<b>PAINT</b>	Very good	Good condition	OK
<b>FLUIDS/FILTERS</b>	1000 hour service if needed and all new lube filters installed.	1000 hour service if needed and all new lube filters installed.	500 hour service if needed and all new lube filters installed.
<b>WARRANTY</b>	6 Month Powertrain/Parts	90 Day Powertrain/Parts	30 Day Powertrain/Parts

**Minor damage = small dents, no tears in metal, side shields & grills on core products.**

**Major leak = any oil dripping within 5 minutes of operation at normal operating temperature. Dust build up around area does not constitute an oil leak.**